As of January 1, 2025, Chiquita Canyon Landfill is closed for the acceptance of waste. Chiquita Canyon, LLC will continue to manage the landfill, including addressing the elevated temperature landfill event that is affecting the northwest corner of the landfill, as well as closure and post-closure activities. While active waste disposal operations have closed, we remain committed to working with federal, state and local regulators on the ongoing reaction mitigation efforts.

News & Alerts

Statement by Chiquita Canyon – Incident Update

The safety of our employees and our neighbors remains our highest priority. The following is an incident update:

English

On Monday, November 16, during a routine drilling operation to install a new gas well at Chiquita Canyon Landfill to help address the elevated temperature landfill event, crews encountered a pressurized pocket within the landfill. This resulted in an above-ground release of gases and particulate material at the drilling location. No liquids were released, and no injuries have been reported. Four individuals were taken to the hospital for a precautionary evaluation. Work at the drilling location was stopped immediately, and the area has been secured.

Chiquita continues to coordinate with state and local regulatory agencies and emergency response personnel. We are providing the following update on air monitoring, our response to this incident, drilling activities, and ongoing management of the elevated temperature landfill event.

Air Monitoring

Air monitoring in the surrounding community has shown no exceedances of Reference Exposure Levels (RELs) for any of the constituents monitored, including benzene, consistent with reporting from the Los Angeles County Fire Department last evening. In addition to Chiquita's community monitoring stations, Chiquita has dispatched a team of air monitors to the surrounding community. Monitoring is ongoing, and results will continue to be shared with regulators and the public.

Chiquita is also conducting air monitoring on site to protect the health and safety of workers involved in the response. Personnel working in and around the affected area are using appropriate personal protective equipment and following established safety protocols.

Incident Response

Chiquita immediately reported the incident to the Los Angeles County Fire Department, and the facility implemented emergency response measures to address the incident and protect the safety of personnel at the Landfill. Approximately 80 personnel were on site at the time of the incident. We have since increased that number to approximately 180 personnel dedicated to incident response and cleanup. We continue to work closely with our regulatory oversight agencies.

Drilling Activities

English

The well installation was part of the work being performed as required by our regulatory agencies. In addition to stopping work at the affected location, Chiquita halted all drilling activities across the landfill as of 4:00 p.m. on Monday. Drilling will not resume until cleanup is complete and Chiquita has conducted a full review of the incident in coordination with our regulators.

Ongoing Management of the Elevated Temperature Landfill Event

We do not expect this situation to impact our overall, ongoing efforts to manage the elevated temperature landfill event. As a precaution, Chiquita took immediate steps to secure the area, including temporarily de-energizing certain electrical power circuits, which resulted in temporary adjustments to some site systems. Chiquita has begun restarting those systems and expects them to return to normal operation as soon as possible.

We will continue to provide updates as more information becomes available.

Translation into Spanish:

The safety of our employees and our neighbors remains our top priority. Below, we present an update on the incident:
El lunes 16 de noviembre, durante una operación rutinaria de perforación para instalar un nuevo pozo de gas en el vertedero Chiquita Canyon —con el fin de abordar el fenómeno de elevación de temperatura en el vertedero—, los equipos de trabajo encontraron una bolsa de gas a presión en el interior del mismo. Esto provocó la liberación, en la superficie, de gases y material particulado en el lugar de la perforación. No se produjo ningún derrame de líquidos ni se han reportado lesiones. Cuatro personas fueron trasladadas al hospital para una evaluación preventiva. Los trabajos en el punto de perforación se detuvieron de inmediato y el área ha sido asegurada.
Chiquita continúa coordinándose con las agencias reguladoras estatales y locales, así como con el personal de respuesta a emergencias. A continuación, ofrecemos una actualización sobre el monitoreo de la calidad del aire, nuestra respuesta ante este incidente, las actividades de perforación y la gestión continua del fenómeno de elevación de temperatura en el vertedero.
Monitoreo de la calidad del aire

English

El monitoreo de la calidad del aire en la comunidad circundante no ha mostrado niveles que superen los Límites de Exposición de Referencia (REL, por sus siglas en inglés) para ninguno de los componentes analizados, incluido el benceno; esto coincide con la información proporcionada anoche por el Departamento de Bomberos del Condado de Los Ángeles. Además de las estaciones de monitoreo comunitarias de Chiquita, la empresa ha desplegado un equipo de monitoreo de la calidad del aire en la zona aledaña. El monitoreo continúa en curso y los resultados seguirán compartiéndose tanto con las autoridades reguladoras como con el público.

Chiquita también está realizando monitoreos de la calidad del aire dentro de las instalaciones para proteger la salud y la seguridad de los trabajadores que participan en la respuesta. El personal que labora en el área afectada y sus alrededores utiliza el equipo de protección personal adecuado y sigue los protocolos de seguridad establecidos.

Respuesta ante el incidente

Chiquita informó de inmediato sobre el incidente al Departamento de Bomberos del Condado de Los Ángeles, y las instalaciones activaron medidas de respuesta a emergencias para atender la situación y salvaguardar la seguridad del personal presente en el vertedero. En el momento del incidente, había aproximadamente 80 personas en el lugar. Desde entonces, hemos aumentado esa cifra a cerca de 180 personas dedicadas a la respuesta ante el incidente y a las labores de limpieza. Seguimos trabajando en estrecha colaboración con los organismos reguladores que supervisan nuestras operaciones.

Actividades de perforación

La instalación del pozo formaba parte de los trabajos que se están llevando a cabo conforme a los requisitos establecidos por nuestras agencias reguladoras. Además de detener los trabajos en el lugar afectado, Chiquita suspendió todas las actividades de perforación en el vertedero a partir de las 4:00 p. m. del lunes. Las perforaciones no se reanudarán hasta que concluyan las labores de limpieza y Chiquita haya realizado una revisión exhaustiva del incidente, en coordinación con los organismos reguladores correspondientes.

Gestión continua del incidente relacionado con el aumento de temperatura en el vertedero

No prevemos que esta situación afecte a nuestras labores generales y continuas para gestionar el incidente relacionado con el aumento de temperatura en el vertedero. Como medida de precaución, Chiquita tomó medidas inmedi

English

asegurar la zona, lo que incluyó la desactivación temporal de ciertos circuitos eléctricos; esto conllevó ajustes provisionales en algunos sistemas de las instalaciones. Chiquita ya ha comenzado a reactivar dichos sistemas y espera que vuelvan a funcionar con normalidad a la mayor brevedad posible.
Seguiremos ofreciendo actualizaciones a medida que dispongamos de más información.

More Articles

Hotel Rooms Available Beginning Today for Designated Val Verde Streets

November 17, 2026

Relief Center Now Open

November 17, 2026

Alert: Resumed Operation of Landfill Gas Collection and Control Equipment on 11/17/2026 by 12:12pm

November 17, 2026

Alert: Resumed Operation of Landfill Gas Collection and Control Equipment on 11/17/2026 by 10:02am

November 17, 2026

Alert: Landfill Gas Collection and Control Equipment Unplanned Down Time on 11/16/2026 at 4:30pm; Resumed Operation on 11/16/2026 by 6:36pm

November 17, 2026

LA County Fire Department Update

November 17, 2026

English

News & Alerts

News

Alerts

Interested in the latest news and updates from Chiquita Canyon?

Subscribe

Want to receive alert notifications? **Sign up**

English

Chiquita Canyon is a 639-acre landfill located in Castaic, California, on State Route 126 in the Santa Clarita Valley.

©2025 A Waste Connections Company. All Right Reserved.

Contact

info@chiquitacanyon.com
Odor Mitigation - (661) 253-5155
Business Office - (661) 257-3655
After Hours - (877) 263-2561
(Bilingual Operators)

29201 Henry Mayo Dr.
Castaic, CA 91384
Get directions

Interested in the latest news and updates from Chiquita Canyon?

Subscribe

English